SYSTEM SUPPORT DIRECTIVE ASR9 SDR-ASR9-008 6310 UPDATE TO EEM 6310.18, CHG. 19, CHAP. 16 Update pages to TI 6310.18

05/25/2004

1. PURPOSE. This system documentation release (SDR) provides a correction to Electronic Equipment Modification (EEM) 6310.18, Electronic Equipment Modification Handbook - Airport Surveillance Radar – 9, Change 19, Chapter. 16, Equipment Modulator Pulse Assembly and Oil Tank Replacement,. dated 8/20/93, to make a correction to Instruction Book, TI 6310.25, ASR-9 System Transmitter Channel A/B (Unit 1/6), paragraph 7.6.8.3.

2. DISTRIBUTION.

- a. This SDR is distributed to selected offices and services within Washington headquarters, the William J. Hughes Technical Center, the Mike Monroney Aeronautical Center, regional Airway Facilities divisions, and Airway Facilities field offices having the following facilities/equipment: ASR-9.
- b. An electronic version and distribution report of this SDR are available on an Intranet site located at http://aos-ext.amc.faa.gov/ under the "Technical Documentation" heading.
- c.To obtain additional hard copies of this publication, contact Printing & Distribution Team, AMI-700B, at (405) 954-6892.
- 3. WITHDRAWALS/CANCELLATIONS. None.
- **4. APPLICATION.** All holders of the Instruction Book, TI 6310.25, ASR-9 System Transmitter Channel A/B (Unit 1/6), are to update their books dated November 2001 with the attached change pages.

SSD PAGE CONTROL CHART

Remove Pages	Dated	Insert Pages	Dated	
<u>SSD TOC</u>				
<u>TI 6310.25</u>				
7-37 and 7-38 u	ındated	7-37 and 7-38	05/25/2004	

DISTRIBUTION: Selected Airway Facilities Field INITIATED BY: ASR-9

and Regional Offices, ZAF-605 Terminal/RDAS

Branch

- **5. CHANGES TO RECORDED DATA.** Enter this SSD number, date, chapter and change number on the appropriate FAA Form 6032-1, Airway Facilities Modification Record.
- **6. ADDRESS CHANGES.** Submit facility address, copy count, and additions or deletions to Carrie Batty via e-mail at Carrie.ctr.Batty@faa.gov.
- **7. RISKS.** If changes are not incorporated, unauthorized configuration may degrade the efficiency of the National Airway Systems (NAS) and the ability to maintain operations.
- **8. STATUS ACCOUNTING.** Providing your equipment is listed in the Facility/Service Equipment Profile (FSEP), the Maintenance Organization has opened a Log Equipment Modification (LEM) record in the Maintenance Management System (MMS). Upon completion of this modification, you are required to close the LEM record and change the Maintenance Action Code (MAC) to a "G" if the modification was completed or a "W" if the modification is not applicable. In the event that your equipment is not listed in the FSEP, it is your responsibility to open the LEM record upon receipt/completion of this Modification. Verify that an "N" is in the "REP COD" field to ensure that the log entry will be upwardly reportable to the national database for National MOD Tracking. The data is to be entered into the LEM as follows:

FAC/SERV: ASR

SHORT NAME: SYS

LOC/IDENT: 53AC

Order No.: SSM-ASR9

Chapter: 008

Change: D

Jamesh Pritchard

For Richard A. Thoma

Program Director for Operational Support

LIST OF APPENDIXES AND ATTACHMENTS

ITEM DESCRIPTION QUANTITY

ATTACHMENT 1 SSD TABLE OF CONTENTS 1

ATTACHMENT 2 INSTRUCTION BOOK CHANGES

Page 2 SDR-ASR9-008

ATTACHMENT 1. SSD TABLE OF CONTENTS

SDR-ASR9-008 Page 1

SYSTEM SUPPORT DIRECTIVE (SSD)

TABLE OF CONTENTS

SYSTEM SUPPORT MODIFICATIONS (SSM)

Document Number	Date Issued	<u>Title</u>
SSM-ASR9-001	04/23/99	ARSR-9 SERIAL INTERFACE SYSTEM
SSM-ASR9-002	02/06/98	TRANSMITTER POWER INTERUPT AND BLOWER MOTOR FUSE
SSM-ASR9-003	10/19/99	REMOVAL OF CIRCUIT BREAKERS FROM MODEM RACK
SSM-ASR9-004	03/13/98	UPGRADE MODE-S INTERFACE SUPPORT
SSM-ASR9-005	04/01/99	PROCESSOR AUGMENTATION CARD PHASE I
SSM-ASR9-006	04/29/98	ASR-9 REMOTE SCIP CIRCUIT BREAKER WIRING CONNECTION
SSM-ASR9-007	06/07/99	ALTERNATE DUAL REDUNDANT MODIFICATION
SSM-ASR9-008	08/02/99	MUFFIN FAN REPLACEMENT
SSM-ASR9-009	TBD	PROCESSOR AUGMENTATION CARD PHASE II
SSM-ASR9-010	CANCELLED	ASR-9 UPDATES
SSM-ASR9-011	03/26/03	SOFTWARE SUPPORT FOR THE WEATHER WSP SYSTEMS PROCESSOR
SSM-ASR9-012	06/19/2003	WEATHER SYSTEMS PROCESSOR INTERFACE TO THE ASR-9
SSM-ASR9-013	06/05/01	ASR-9 SERIAL INTERFACE SYSTEM (ASIS) PHASE II
SSM-ASR9-014	TBD	ANOMALOUS PROPAGATION (AP) FILTER
SSM-ASR9-015	TBD	UPDATE PROCOMM PLUS SCRIPTS
SSM-ASR9-016	07/14/03	ASR-9 SERIAL INTERFACE SYSTEM (ASIS) PHASE II DUAL BOARD

SSD-TOC-ASR9 i

SYSTEM TECHNICAL RELEASES (STR)

Document Number	Date Issued	<u>Title</u>
STR-ASR9-001	02/06/98	DELIVERY OF AIRPORT SURVEILLANCE RADAR-9 PROCOMM SOFTWARE UPDATE
STR-ASR9-002	12/29/98	DELIVERY OF AIRPORT SURVEILLANCE RADAR-9 PROCOMM SOFTWARE UPDATE VERSION 5.0
STR-ASR9-003	11/29/99	DELIVERY OF AIRPORT SURVEILLANCE RADAR-9 SOFTWARE UPDATE VERSION 6.0
STR-ASR-9-004	12/15/99	ASR-9 VARIABLE SITE PARAMETERS AND PROGRAMMABLE ALARM THRESHOLD/FILTER BASELINE
STR-ASR9-004A	06/20/01	ASR-9 VARIABLE SITE PARAMETERS AND PROGRAMMABLE ALARM THRESHOLD BASELINE UPDATES

SYSTEM DOCUMENTATION RELEASES (SDR)

Document Number	Date Issued	<u>Title</u>
SDR-ASR9-001	CANCELLED	BY SDR-ASR9-002
SDR-ASR9-002	CANCELLED	BY SDR-ASR9-003
SDR-ASR9-003	05/09/02	ASR-9 TECHNICAL INSTRUCTION BOOKS UPDATE AND REISSUE OF ASR- 9 TI CD ROM

ii SSD-TOC-ASR9

ATTACHMENT 2. INSTRUCTION BOOK CHANGES

SDR-ASR9-008 Page 1

05/25/2004 TI 6310.25 SDR-ASR9-008

7.6.7.5 Related Alignment Procedures. After replacing charging switch A10, refer to paragraph 7.8.5.6 and perform the peak power output adjustment. At the conclusion of the alignment procedures, refer to paragraph 3.2.3 to return transmitter to system control.

7.6.8 Trigger Amplifier A11

The following instructions describe how to remove trigger amplifier A11 and how to check out and install a replacement unit. See figure 11-11, sheet 1 to locate trigger amplifier A11.

- **7.6.8.1 Equipment Required.** An oscilloscope and an ohmmeter are required.
- **7.6.8.2 Preliminary Operations/Safety Precautions.** Proceed as follows:

WARNING

Inadvertent application of transmitter high voltage can occur after circuit breakers CB1 and CB2 are turned on. To prevent inadvertent transmitter high voltage turn on, access RMS SYSTEM CONTROL PANEL menu (0.1.1) and set HIGH VOLTAGE OFF for the appropriate channel transmitter.

- 1. Refer to paragraph 3.2.1 to place transmitter in maintenance mode.
- 2. Turn off HIGH VOLTAGE POWER circuit breaker CB1 and AUXILIARY POWER circuit breaker CB2.
- 3. Engage circuit breaker lock on power distribution panel and use key to open right bay inner door.
- **7.6.8.3 Removal Procedure.** See figure 11-11, sheet 4 for connector location and detail of latching mechanism, and proceed as follows:
 - 1. Disconnect wiring connector from J1 on front of trigger amplifier A11.
 - 2. Turn grip adjust knob counterclockwise to loosen latch, then turn latch lever to disengage latch.
 - 3. Lower front of trigger amplifier A11 to expose rear handle.
 - 4. Lift trigger amplifier A11 clear of cabinet.
- **7.6.8.4 Pre–Installation Checks.** Before a replacement trigger amplifier A11 is permanently installed, various pre–installation checks must be performed to verify that no equipment problems exist that might cause early failure of the new unit. To perform the checks, proceed as follows:
 - 1. Check diodes, RBDTs, etc., in new A11 prior to installation with ohmmeter.
 - 2. Press both release knobs at bottom of MPA A12 and pull assembly out of cabinet, approximately 6 inches.
 - 3. Remove plug W05P2 from connector 12J3 located on modulator pulse assembly A12 top cover. Jumper pins 9 and 22 on P3 to disable the modulator interlock alarm (see figure 11-5, sheet 4). Leave disconnected during this test procedure.
 - 4. Remove charging switch A10. Install replacement trigger amplifier A11.
 - 5. Connect wiring connector to J1 on front of replacement trigger amplifier A11. Close right bay inner door.

- 6. Turn on and observe trigger amplifier A11 test points:
 - a. Synchronize oscilloscope at CPI PR START jack (J6) on target i-f panel assembly A1 in Radar Receiver/Processor Channel A/B (Unit 2/5). Connect oscilloscope channel A input to all A1TP16 and connect oscilloscope channel B input to A11A1TP6.
 - Turn on AUXILIARY POWER circuit breaker CB2 and HIGH VOLTAGE POWER circuit breaker CB1.
 - c. At trigger amplifier A11, observe trigger spacing of 740-microsecond interval from start of the charge trigger at A11A1TP16 to the start of the discharge trigger at A11A1TP6.
 - d. Turn on high voltage, after preheat is completed.
 - e. Expand triggers for a presentation with no jitter or lines going through presentation as shown in figure 7-3, examples A and B.
 - f. Look for a clean, open waveform on both test points for a one-minute period.
 - g. Turn off high voltage.
- 7. Observe trigger amplifier A11 test points A1TP8 and A1TP14:
 - a. Set oscilloscope for 2 milliseconds sweep time.
 - b. Turn on high voltage.
 - c. Observe the primary current (A11A1TP8) and RBDT stack voltage (A11A1TP14) for uniformity in voltage as shown in figure 7-3, examples E and F.
 - d. Expand waveforms E and F as shown in figure 7-3.
 - e. Monitor A11A1TP8 and A11A1TP14 for 30 minutes with high voltage on.
 - f. Observe A11A1TP14 for minimal droops at the trailing edge (discharge time). Both waveforms should show consistency from pulse to pulse.

NOTE

Some shift may be observed at the end of the sweep due to fill pulse or scope response to variable interval.

- g. If any disconinutive exists in waveform at A11A1TP14, then a possible defect exists in the trigger amplifier under test or the synchronizer.
- h. If any discontinuity exists in waveform at A11A1TP14, then a possible defect exists in the trigger amplifier under test or the charging switch.
- i. Turn off HIGH VOLTAGE.
- 8. Turn off HIGH VOLTAGE POWER circuit breaker CB1 and AUXILIARY POWER circuit breaker CB2.
- 9. Remove the trigger amplifier under test and verify the front–to–back resistance of RBDTs (greater than 5:1).
- 10. Reconnect plug P3 (removed in step 3) to A12J3 located on top of modulator pulse assembly.
- 11. If no problems were encountered during this testing, reasonable assurance exists that the trigger amplifier is ready for permanent installation using the procedure in paragraph 7.6.8.5.